## **DMV Lane Technician Observation Report**

DMV Technician: Smith James P	osition: For 2				
Station: New Castle Date: 6-7-13	Time: 11:41				
Vehicle Make Ehre Model Corvette	Y	Year 2003			
GVWR: - Fuel Type: 6 45 Registrat	ion Nur	nber	25	8241	
Auditor: Over du le . Covert / Overt (circle one)					
		YES	NO	N/A	
1. Did technician check vehicle paper work and verify VIN numb	er?	·L			
2. Was Emissions testing required?		1			
a) Was Emissions testing performed using OBD?		1			
b) Was Emissions testing performed using Analyzer Probe?					
c) Was Emissions testing performed using Paddle(s)?					
d) Was Emissions testing performed using Clip?					
3. Was Catalytic Converter inspection required?				1	
a) Was Catalytic Converter inspection performed?					
4. Was Fuel Tank pressure testing required?				_	
a) Was Fuel Tank pressure testing performed?					
5. Was Fuel Cap pressure testing required?				-	
a) Was Fuel Cap pressure testing performed?					
6. Is this test a <b>Re-check</b> from a prior failure?			-		
a) Which re-check test is being performed? 1 2 3 (circle one)					
b) If this is re-check #3, was repair paperwork verified for waiv	er?				
New Castle and Kent Counties Only					
7. Was Two-Speed Idle testing required?			_		
a) Was Two-Speed Idle testing performed?					
Sussex County Only					
8. Was Curb Idle testing required?					
a) Was Curb Idle testing performed?					
Comment:					
Lane Supervisor Signature:					

Revised 04/12/2013

## **DMV Lane Technician Observation Report**

MV Technician: Legrande Mike Position Tor 2							
Station: New Costh Date: 6-7-13 Time:	11						
Vehicle Make: Togora Model RAUY	Year						
GVWR: 4535 Fuel Type: 645 Registration N	GVWR: 4531 Fuel Type: 645 Registration Number: 80735						
Auditor: Coverdale Covert / Overt (circle one)							
	YES	NO	N/A				
1. Did technician check vehicle paper work and verify VIN number?	V						
2. Was Emissions testing required?	1						
a) Was Emissions testing performed using OBD?	1						
b) Was Emissions testing performed using Analyzer Probe?							
c) Was Emissions testing performed using Paddle(s)?							
d) Was Emissions testing performed using Clip?							
3. Was Catalytic Converter inspection required?			1				
a) Was Catalytic Converter inspection performed?							
4. Was Fuel Tank pressure testing required?			4				
a) Was Fuel Tank pressure testing performed?							
5. Was Fuel Cap pressure testing required?			_				
a) Was Fuel Cap pressure testing performed?							
6. Is this test a <b>Re-check</b> from a prior failure?		4					
a) Which re-check test is being performed? 1 2 3 (circle one)							
b) If this is re-check #3, was repair paperwork verified for waiver?							
New Castle and Kent Counties Only							
7. Was Two-Speed Idle testing required?	7-1	1					
a) Was Two-Speed Idle testing performed?							
Sussex County Only							
8. Was Curb Idle testing required?							
a) Was Curb Idle testing performed?							
Comment:							
Lane Supervisor Signature:							

Revised 04/12/2013